


## HALDEX MODUL X

MODUL X



<b>HALDEX MODUL X</b>		VP CENA	+PDV
<p><b>18955</b></p> <p>SET KLIZAČA</p> <p>HALDEX 93299</p>	<p>SAF osovina SMB osovina</p> <p>DANA osovina GIGANT osovina</p> <p>VOLVO RENAULT</p>  <p>Ø35x64</p> <p>M14/2x42</p> <p>Ø42x23</p> <p>Ø28/56</p>	<p><b>6.110</b></p>	<p><b>7.332</b></p>
<p><b>18541</b></p> <p>SET POTISKIVAČA I CENTRALNI VIJCI</p>		<p><b>2.510</b></p>	<p><b>3.012</b></p>
<p><b>18505</b></p> <p>SET GUMICA POTISKIVAČA</p> <p>HALDEX 91011</p>		<p><b>1.930</b></p>	<p><b>2.316</b></p>
<p><b>18952</b></p> <p>SET VRATILA ŠTELERA</p> <p>HALDEX 94892</p>		<p><b>680</b></p>	<p><b>816</b></p>
<p><b>18327</b></p> <p>KUĆIŠTE</p>		<p><b>3.980</b></p>	<p><b>4.776</b></p>

HALDEX MODUL X		VP CENA	+PDV
<p><b>18600</b></p> <p>MEHANIZAM ŠTELERA</p>		<p><b>4.560</b></p>	<p><b>5.472</b></p>
<p><b>18601</b></p> <p>SREDNJI ZUPČANIK</p>		<p><b>1.480</b></p>	<p><b>1.776</b></p>
<p><b>18602</b></p> <p>ZUPČANIK ŠTELERA</p>		<p><b>670</b></p>	<p><b>804</b></p>
<p><b>18603</b></p> <p>RUČNI ŠTELER</p>		<p><b>2.350</b></p>	<p><b>2.820</b></p>
<p><b>18403</b></p> <p>KLACKALICA</p>		<p><b>4.020</b></p>	<p><b>4.824</b></p>
<p><b>18404</b></p> <p>OSOVINICA KLACKALICE</p>		<p><b>500</b></p>	<p><b>600</b></p>

HALDEX MODUL X		VP CENA	+PDV
<p><b>18596</b></p> <p>SET LEŽAJA</p>		<p><b>1.180</b></p>	<p><b>1.416</b></p>
<p><b>18595</b></p> <p>SET LEŽAJA</p>		<p><b>800</b></p>	<p><b>960</b></p>
<p><b>18592</b></p> <p>PLOČA MEHANIZMA</p>		<p><b>760</b></p>	<p><b>912</b></p>
<p><b>18519</b></p> <p>POKLOPAC MEHANIZMA</p>		<p><b>2.680</b></p>	<p><b>3.216</b></p>
<p><b>18599</b></p> <p>STEGA MEHANIZMA</p>		<p><b>1.430</b></p>	<p><b>1.716</b></p>
<p><b>HALDEXX</b></p> <p>REPARACIONI SET</p> <p>16850</p> <p>U SETU NEMA:</p> 	 <p>(18599+18592+18327+18403+18600+18601+18602+18603+ +18595+18596+18505+18519+18404+18541+18952)</p>	<p><b>29.530</b></p>	<p><b>35.436</b></p>

## HALDEX MODUL T






MODUL T



## HALDEX MODUL T

VP CENA

+PDV

<p><b>18020</b></p> <p>SET KLIZAČA</p> <p>HALDEX 95397 SAF 3434386100</p>	<p>SAF osovina</p>  <p>Ø35x120 M16/1,5x80</p> <p>Ø35,5x87 M16/1,5x80</p>	<p><b>4.270</b></p>	<p><b>5.124</b></p>
<p><b>18052</b></p> <p>SET ZAŠTITA ISPOD ŠTELERA</p>		<p><b>2.650</b></p>	<p><b>3.180</b></p>
<p><b>18052/5</b></p> <p>ZAŠTITA ISPOD ŠTELERA 18004</p>		<p><b>800</b></p>	<p><b>960</b></p>
<p><b>18033</b></p> <p>SET RESETA</p>	 <p>(18054/5+18057/5+18056/5)</p>	<p><b>1.610</b></p>	<p><b>1.932</b></p>
<p><b>18050</b></p> <p>MEHANIZAM ŠTELERA</p>		<p><b>4.420</b></p>	<p><b>5.304</b></p>

HALDEX MODUL T		VP CENA	+PDV
<p><b>18088</b></p> <p>SET LEŽAJA ŠTELERA</p>		<b>1.180</b>	<b>1.416</b>
<p><b>18089</b></p> <p>SET LEŽIŠTA LEŽAJA ŠTELERA</p>		<b>2.650</b>	<b>3.180</b>
<p><b>18089/5</b></p> <p>LEŽIŠTE LEŽAJA ŠTELERA 18066</p>		<b>800</b>	<b>960</b>
<p><b>18013</b></p> <p>KALIBRACIONI VIJAK</p>		<b>3.240</b>	<b>3.888</b>
<p><b>18014</b></p> <p>KUĆIŠTE ŠTELERA</p>		<b>3.540</b>	<b>4.248</b>
<p><b>18012</b></p> <p>KUĆIŠTE</p>		<b>2.650</b>	<b>3.180</b>



HALDEX MODUL T		VP CENA	+PDV
<b>18065</b> SET LEŽAJA		<b>860</b>	<b>1.032</b>
<b>18067</b> SET LEŽAJA		<b>1.150</b>	<b>1.380</b>
<b>18010</b> KLACKALICA		<b>3.540</b>	<b>4.248</b>
<b>18021</b> SET KLJUČEVA ŠTELERA		<b>1.920</b>	<b>2.304</b>
<b>18021/5</b> KLJUČ ŠTELERA 18009		<b>580</b>	<b>696</b>
<b>18059</b> SET ZAŠTITNIH KAPA		<b>450</b>	<b>540</b>



## HALDEX MODUL T

VP CENA

+PDV

<p><b>18059/5</b></p> <p>ZAŠTITNA KAPA 18008</p>		<p><b>140</b></p>	<p><b>168</b></p>
<p><b>18058</b></p> <p>SET ZAŠTITA PRIKLJUČKA</p>		<p><b>1.030</b></p>	<p><b>1.236</b></p>
<p><b>18058/5</b></p> <p>ZAŠTITA PRIKLJUČKA 18006</p>		<p><b>310</b></p>	<p><b>372</b></p>
<p><b>HALDEX</b></p> <p>REPARACIONI SET 18030</p> <p>U SETU NEMA:</p>  <p> <small>             Ø35x120    Ø35,5x87              M16/1,5x80    M16/1,5x80           </small> </p>	 <p>(18052/5+18010+18067+18012+18065+18013+ +18014+18050+18021/5+15707)</p>	<p><b>20.830</b></p>	<p><b>24.996</b></p>