


Z-CAM

Z-CAM



		Z-CAM	VP CENA	+PDV
<p>14832</p> <p>KALIBRACIONO VRATILO</p> <p>MERITOR ST4014 MERITOR ST4023 MERITOR A164061 MERITOR 68192565</p>	 <p>LEVO</p>		2.850	3.420
<p>14831</p> <p>KALIBRACIONO VRATILO</p> <p>MERITOR ST4013 MERITOR ST4024 MERITOR A64062 MERITOR 68192566</p>	 <p>DESNO</p>		2.850	3.420
<p>14842</p> <p>KALIBRACIONI ZUPČANIK</p> <p>MERITOR A64052 MERITOR 68191510</p>	 <p>LEVI</p>		1.250	1.500
<p>14841</p> <p>KALIBRACIONI ZUPČANIK</p> <p>MERITOR A64055 MERITOR 68191511</p>	 <p>DESNI</p>		1.250	1.500
<p>15076</p> <p>KALIBR.ZUPČANIK SA OPRUGOM</p> <p>MERITOR ST1038 MERITOR 68191510</p>	 <p>LEVI</p>		2.530	3.036

Z-CAM		VP CENA	+PDV
15075 KALIBR.ZUPČANIK SA OPRUGOM MERITOR ST1039 MERITOR 68191510 DESNI		2.530	3.036
15095 REVERSE LOCK MERITOR ST1036 MERITOR ST4021 LEVI		810	972
15094 REVERSE LOCK MERITOR ST1037 MERITOR ST4020 DESNI		810	972
14840 POPREČNO KALIBRACIONO VRATILO MERITOR SP8540 MERITOR ST4018		790	948
15079 SET BRAVICE MERITOR ST1035 MERITOR ST4022 23 ZUBA		3.010	3.612

Z-CAM		VP CENA	+PDV
<p>15078</p> <p>SET BRAVICE</p> <p>MERITOR ST1034</p> <p style="font-size: 1.2em;">14 ZUBA</p>		3.010	3.612
<p>15080</p> <p>POVRATNA ČIVIJA ŠTELERA</p> <p>MERITOR 137075 MERITOR 68192487</p>		730	876
<p>15081</p> <p>ČIVIJA ŠTELERA</p> <p>MERITOR 137074 MERITOR 64225252</p>		290	348
<p>16029</p> <p>ZAPTIVAČ</p> <p>MERITOR 166063 MERITOR 68191066</p>		310	372
<p>15083</p> <p>SET ZAPTIVAČA</p> <p>MERITOR ST1053 MERITOR ST4025</p>		1.570	1.884

Z-CAM		VP CENA	+PDV
<p>15082</p> <p>POKLOPAC ŠTELERA</p> <p>MERITOR 68191065</p>		850	1.020
<p>15084</p> <p>CRVENA GUMICA</p> <p>MERITOR 68192410</p>		350	350
<p>14999</p> <p>POVRATNA OPRUGA</p> <p>MERITOR 167090 MERITOR 68192115</p>		2.210	2.210
<p>ZCAM</p> <p>REPARACIONI SET</p>	 <p>(14832+14831+15084x2+14840+15081x2+15083)</p> <p>23 ZUBA</p> <p>14 ZUBA</p> <p>15079</p> <p>15078</p> <p>LEVI TOČAK</p> <p>14842 15095</p> <p>DESNI TOČAK</p> <p>14841 15094</p>	14.410	17.292